PATENT & 24 PASSIVATION 22 . NL STEP 1 PASSIVATION ĄL 30 Ni PASSIVATION STEP Z AL 60 58 BUTZ STEP 3 NL PASSIVATION AL 30 -62 NL STEP 4 PASSIVATION AL 66 Ni BLTZ NC PASSIVATION STEP 5 AL AL 36 NL 30 32 34 BLTZ STEP6 NL NL PASSIVATION AL AL F16.3

FEB 1 2004 BEENT & TRADES

